
City of Baltimore Wet Smoke and Dyed	Page 1 of 1	
Sewershed: Gwynns Falls Company: Savin		Date: <u>7/16/2009</u>
Test to be performed: Smoke Dyed Water X	Ground Condition: Dry ✓ Damp □ Wet □	Supervisor: <u>JAW</u>
Manhole_ID: S05O028MH	Test ID: <u>D1032-002026</u>	Notification Made: NA (Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S05O028MH
0			Water Level	
52.5	02		Tap Factory	From 413 Augusta
52.5			Dye Test Visible	@ TF - toilet
52.5			Dye Test Not Visible	@ TF - downspout
56.29999924			Manhole	S05O030MH
56.29999924			End of Survey	DYR TAST COMPLETED